

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Tuesday, February 26, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Montgomery County MP 227 St#12035+19 &amp; 12031+56 MP 228 St#12076+95</b>	Spread H	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- |   |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?                                                                                                                             | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


**Comments:**

- Inspected designated streams included: S-G36, S-G38, and S-G40. All ECD were in place near all the streams, no impacts were observed at the time of the inspection.
- At designated stream S-G39 triple stack at stream bank required re installation and had been previously reported in extended corrective actions required, crews were on site for the repair on 2-27-19. No impacts were observed at the time of the inspection.

**Recommended Corrective Action:** Maintain all controls per the annual standards and specs.

**Deadline:** within the 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 3-4-19

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 26, 2019

- Fig. 1 Area near designated stream S-G36 has been temporarily stabilized and controls are in place.



- Fig. 2 Area near designated stream S-G40 has been temporarily stabilized and controls are in place.



- Fig. 3 Area near designated stream S-G39 has been temporarily stabilized and triple stack was noted for repair.



- Fig. 4 Area near designated stream S-G38 has been temporarily stabilized and controls are in place.

